



TECHNICAL BULLETIN

September 2011

NOTICE OF UL/ULC STANDARD CHANGE THAT AFFECTS EXTINGUISHER RATINGS

In 2002, Underwriters Laboratories (UL) and Underwriters Laboratories Canada (ULC) jointly published a "harmonized" Standard 711 for the fire rating tests of hand portable and wheeled fire extinguishers. Prior to this change, the U.S. and Canadian Standards had different test requirements for the Class A rating, the main difference being that the ULC Standard specified a larger wood crib for fire tests. In the new harmonized Standard the larger ULC wood crib is the adopted requirement. This change to the Standard has made it necessary for all fire extinguisher manufacturers to undergo retests of many of their current products to establish Class A ratings to the new Standard. The results of this retesting were that the current Class A ratings on a few fire extinguishers have been adjusted lower. For example, an extinguisher that currently carries a 20A UL rating may be reclassified to a 6A rating under the more rigorous bi-national Standard.

Industry compliance to this new Standard is scheduled for February 14, 2011. It is anticipated that all of the fire extinguisher manufacturers will announce their new ratings by this date. Please see the Table on the following page for the new ratings of the affected Buckeye products.

Three important points to understand about this change;

1. Buckeye's fire extinguishers have not been changed in design or fire fighting capabilities. The extinguishers you have been buying before the February 14th implementation date will be the same as the ones you buy after that date. Model/Part Numbers are unaffected. Ratings may be lower on a few product models as a reflection of the more rigorous tests but the extinguishing potential remains the same (See Table).
2. The revised ratings will apply to extinguishers manufactured after the implementation date. Existing extinguishers in the field, in your inventory, and in Buckeye's inventory will still carry the rating of the previous UL Listing.
3. The NFPA 10 Standard will not be changed to reflect the UL/ULC harmonized Standard. All of its current requirements regarding Class A extinguishers remain in effect.

Thank you for your attention to this significant change in the fire protection industry. It is important that you understand the impact this change may have on your customers so that you can continue to effectively serve their fire protection needs. If you should have questions regarding this change please contact your Buckeye Sales Representative.

Model	Previous Rating	New Rating
20S ABC	20-A:120-B:C	6-A:120-B:C
30S ABC	20-A:160-B:C	6-A:160-B:C
A-50-SP	30-A:160-B:C	10-A:160-B:C
A-150-SP	40-A:240-B:C	30-A:240-B:C
A-150-RG	40-A:240-B:C	30-A:240-B:C
A-150-PT	40-A:240-B:C	30-A:240-B:C
A-350-RG	40-A:320-B:C	30-A:320-B:C
A-350-PT	40-A:320-B:C	30-A:320-B:C

Note: The new ratings are applicable to all part number configurations of the listed model.

All models not listed in the Table retain their current rating.